

This document is a tool to help ensure appropriate due diligence has been taken prior to site clearance/works. Evidence is required to demonstrate all tree clearance has been suitably reviewed and can be justified.

Note: this document should be read in conjunction with the HS2 Tree Panel Terms of Reference

	Name	Signature		Date
Application made by:	MDJV			15/05/2024
Location (Sector/Site Name):	Camden Construction Skill Centre			
LAA/LAP/Site Reference	N/A			
Work Package number:	N/A			
Date of Tree Panel:	Camden Construction Skill Centre			
Site Description:	Camden Construction Skill Centre			
Reason for clearance:	Removal of a broken branch for safety reasons.			
Drawing Reference No.:	N/A but annotated photographs as below section			
	Yes	No	N/A	Comments
Has the Stage 1 Survey been completed and logged on the Register	X			
	Yes	No	N/A	Comments
Has the Stage 2 Survey been completed with retention and protection measures logged on the Register			X	
Have all practicable means to negate need for works to tree been investigated? Please provide details	Yes, the proposed works are undertaken for safety reasons and will only remove the branches that are already broken.			

Site Sketch/ Diagram / Photos attached:

Photo1: Photo illustrating the point where the branch is broken.




Photo 2: Exclusion zone and hanging branch from below



Diagram No.1: Location Plan

Trees identified for removal

Tree ID	Species – Common Name (<i>scientific name</i>)	Height (m)	Diameter at Breast Height (DBH) (cm) @1/5m	Age
T095	Aspen (Populus tremula)	16.5	55	20+

Tree Panel Outcomes

		Proposal Endorsed/Not Endorsed:	Endorsed
Conditions			