

This document is a tool to help ensure appropriate due diligence has been taken prior to site clearance/works. Evidence is required to demonstrate all tree clearance has been suitably reviewed and can be justified.

**Note:** this document should be read in conjunction with the HS2 Tree Panel Terms of Reference


	<b>Name</b>	<b>Signature</b>		<b>Date</b>
Application made by:	SCSJV			22/08/2022
<b>Location (Sector/Site Name):</b>	Addison Lee Office, Euston Approaches, HS2			
<b>LAA/LAP/Site Reference</b>	LAP00640			
<b>Work Package number:</b>				
<b>Date of Tree Panel:</b>	26/08/2022			
<b>Site Description:</b>	Addison Lee Compound			
<b>Reason for clearance:</b>	Pruning of the fig tree is required as the branches are currently growing over the "Sycamore Room", within the Addison Lee compound. The "Sycamore Room" building needs to be demolished and SCS cannot access this building on some sides due to the tree over growing.			
<b>Drawing Reference No:</b>				
	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
<b>Has the Stage 1 Survey been completed and logged on the Register</b>		X		
	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
<b>Has the Stage 2 Survey been completed with retention and protection measures logged on the Register</b>		X		


<p><b>Have all practicable means to negate need for works to tree been investigated? Please provide details</b></p>	<p>The original proposal was for the whole tree to be removed, this has been revised and the tree instead will be pruned.</p> <p>The reasons this pruning is required are as below:</p> <ul style="list-style-type: none"> <li>• SCS need to demolish the building the “Sycamore room” building, the tree currently overgrows the building and limits access to some sides.</li> <li>• In order to do this demolition, Network Rail require that there is a clear line of sight during the demolition, to ensure safety of the railway lines below.</li> <li>• Clear access and egress is needed for scaffolding installation around the perimeter of the ‘Sycamore room’.</li> <li>• At present the overhanging branches prevent the safe installation of new fence panels (podiums, tools, equipment etc)</li> <li>• Overhanging branches need to be removed for the new cabin installation.</li> </ul>
---	---

**Trees Affected and Scope of Works:** One tree located within the SCS Addison Lee Compound

Tree ID	Species
Tree No. 1 Addison Lee	Fig tree (ficus carica)

Site Sketch/ Diagram / Photos attached







Tree ID

Photo

Fig tree (ficus carica)



**Tree Panel Outcomes**

		<b>Proposal Endorsed/Not Endorsed:</b>	Endorsed
<b>Conditions</b>	N/A		