



LBC Tree Panel Review of Works



This document is a tool to help ensure appropriate due diligence has been taken prior to site clearance/works. Evidence is required to demonstrate all tree clearance has been suitably reviewed and can be justified.

Note: this document should be read in conjunction with the HS2 Tree Panel Terms of Reference


	Name			Sigi	nature		Date
Application made by:	MDJV						24/08/2022
Location (Sector/Site Name): LAA/LAP/Site Reference		Interim Taxi Rank					
		LP00862					
Work Package number:		N/A					
Date of Tree Panel:						26/08/2022	
Site Description:		Interim Taxi Rank					
Reason for clearance:				cated within the footpath area of the project. The level of the quires build-up of 300mm of soil level around this tree.			
Drawing Reference No.:		NA but	annota	ated p	ohotographs	as below section	
		Yes	No		N/A	Comments	
_		.,					
Has the Stage 1 Surve completed and logged Register	•	X					
completed and logged	•	Yes	No		N/A	Comments	
completed and logged	ey been		No		N/A X		otection not relevant in








Site Sketch/ Diagram / Photos attached



Photograph No.1



Drawing No 1:

Photograph No 1: Illustrating the view looking East at tree LP00862_T_F110 from within Interim Taxi Rank

Drawing No 1: Illustrates the location of the tree within the Interim Taxi Rank locality

Trees identified for removal

Tree ID	Species – Common Name (scientific name)	Height (m)	Diameter at Breast Height (DBH) (cm) @1/5m	Age	RPA Radius (m)
LP00862_T_F110	London plane (<i>Platanus</i> x acerifolia)	11	23	SM	2.76





LBC Tree Panel Review of Works



Tree Panel Outcomes

		Proposal Endorsed/Not Endorsed:	Endorsed
Conditions	N/A		