



This document is a tool to help ensure appropriate due diligence has been taken prior to site clearance/works. Evidence is required to demonstrate all tree clearance has been suitably reviewed and can be justified.

Note: this document should be read in conjunction with the HS2 Tree Panel Terms of Reference

	Name		S	ignature		Date	
Application made by:	SCSjv					12/04/2024	
Location (Sector/Site Name):		Euston Approaches – Hampstead Road Utilities works					
LAA/LAP/Site Reference		Grid Reference TQ 29115 83121					
Work Package number:		n/a					
Date of Tree Panel:		18/04/2024					
Site Description:		Xavier House – Euston Approaches Site boundary					
Reason for clearance:		A Crown reduction of the fig tree is required as the branches are currently growing over the compound, and potentially causing damage to the wall and fence line above the live railway.					
Drawing Reference No.:		Hampsted Road, Arboricultural Survye					
		Yes	No	N/A	Comments		
Has the Stage 1 Survey completed and logged Register	•	Х					
		Yes	No	N/A	Comments		
Has the Stage 2 Survey completed with retention protection measures log the Register	on and	Х					
Have all practicable me negate need for works been investigated? provide details		Yes, this is for information as we will arrange for the works to be completed if needed. This endorsement would be used if works are unable to be undertaken by the resident. Pre-approval is sought should potential damage to SCS structures or a safety risk be identified.					







Tree Data:

Tree ID	Species – Common Name (scientific name)	Height (m)	Diameter at Breast Height (DBH) (cm) @1/5m	Age	RPA Radius (m)
T001	Fig - (Ficus carica)	12	60	М	6

Site Sketch/ Diagram / Photos:









Tree Panel Outcomes

		Proposal	Endorsed with conditions			
		Endorsed/Not Endorsed:				
Conditions	Canopy to be reduced by SC	Canopy to be reduced by SCS only if required due to safety risk and if the property				
	owner is unable to do the wo	owner is unable to do the work.				