

This document is a tool to help ensure appropriate due diligence has been taken prior to site clearance/works. Evidence is required to demonstrate all tree clearance has been suitably reviewed and can be justified.


Note: this document should be read in conjunction with the HS2 Tree Panel Terms of Reference

	Name	Signature			Date
Application made by:					
Location (Sector/Site Name):	Euston Station				
LAA/LAP/Site Reference	S311_053				
Work Package number:	N/A				
Date of Tree Panel:	22/07/25				
Site Description:	Euston Square Gardens west, Euston				
Reason for clearance:	Pruning of 3 trees that are impacting the passage of buses, taxis and people respectively				
Drawing Reference No.:	N/A				
	Yes	No	N/A	Comments	
Has the Stage 1 Survey been completed and logged on the Register	Y				
	Yes	No	N/A	Comments	
Has the Stage 2 Survey been completed with retention and protection measures logged on the Register	Y				
Have all practicable means to negate need for works to tree been investigated? Please provide details	This is regular maintenance pruning to ensure that tree branches are not damaged by cars and buses.				


Tree Data:

Tree ID	Species – Common Name (scientific name)	Height (m)	Diameter at Breast Height (DBH) (cm) @1/5m
To28	London plane (Platanus x acerifolia)	20	54
To31	Common Lime (Tilia Europea)	Stump 0.15m, branch regrowth approx. 1.5m	N/A
To36	London plane (Platanus x acerifolia)	Stump 0.15m, branch regrowth approx. 3m	N/A

Site Sketch/ Diagram / Photos:




To28 – removal of branch hitting the top of passing buses



T031



T036



Tree Panel Outcomes

		Proposal Endorsed/Not Endorsed:	To28 and To36 are endorsed. To31 not endorsed
Conditions	To36: MDjv to keep pruning to a minimum and set up a regular maintenance regime To31: AS and PL to visit the tree and feedback on whether or not to prune		